



* Lead of actuator Approx. $2^{\circ} 8' 34''$

TS-411

Goniometer stage 40×40

 CHUO PRECISION INDUSTRIAL CO., LTD.

rev4

*Mounting screw : Hexagon socket head cap screw M3, 4 screws