



4-3.5 mounting hole,
6 deep counterbore

* Lead of actuator Approx. 1° 20'

TS-412

Goniometer stage 40×40

 CHUO PRECISION INDUSTRIAL CO., LTD.

rev.4

*Mounting screw : Hexagon socket head cap screw M3, 4 screws